








x5




x3













x1




















x1








Ax1 	Bx1  $\frac{590 \times 515 \times 110}{23.2 \times 20.3 \times 4.3}$	Cx1 	Dx4 	Ex8  $M6 \times \frac{30}{1.2}$
Fx8  $M6 \times \frac{40}{1.6}$	Gx16  M6	Hx8  M6	Ix1 	Jx1 
Kx1  $\frac{580 \times 310 \times 60}{22.8 \times 12.2 \times 2.4}$	Lx1  $\frac{510 \times 310 \times 60}{20.1 \times 12.2 \times 2.4}$	Mx1  $\frac{580 \times 580 \times 60}{22.8 \times 22.8 \times 2.4}$		



Ax1  $\frac{695 \times 515 \times 110}{27.4 \times 20.3 \times 4.3}$	Bx1 	Cx4 	Dx4  $M6 \times \frac{30}{1.2}$
Ex8  $M6 \times \frac{40}{1.6}$	Fx12  M6	Gx8  M6	Hx1  M6
Ix1  M6	Jx1  $\frac{680 \times 310 \times 60}{26.8 \times 12.2 \times 2.4}$	Kx1  $\frac{680 \times 580 \times 60}{26.8 \times 22.8 \times 2.4}$	
1 		2 	
3 			

Ax1 	Bx1  $\frac{665 \times 20 \times 215}{26.2 \times 0.8 \times 8.5}$	Cx1  $\frac{642 \times 20 \times 215}{25.3 \times 0.8 \times 8.5}$	Dx4 
Ex7  $M6 \times \frac{30}{1.2}$	Fx8  $M6 \times \frac{40}{1.6}$	Gx15  M6	Hx8  M6
Ix1  M6	Jx1  M6	Kx1  $\frac{680 \times 680 \times 60}{26.8 \times 26.8 \times 2.4}$	
1 	2 		
3 	4 		

Ax1 	Bx4 	Cx4 	Dx1  M6
Ex8  M6x $\frac{40}{1.6}$	Fx1  M6	Gx8  M6	Hx8  M6

