

On-Screen Display

The monitor functions can be controlled with the On Screen Display.

Current setting will be saved and OSD will be turned off when the keys are not touched for a period of time (please see OSD section).

Hot Key Operation

Auto	Exit	◀	▶	Enter	⏻
1. Press 0-1 sec → auto adjustment 2. Press over 1 sec → input menu	I-style Video Mode	ECO Mode	Volume	OSD Main Menu	Power

Menu Operation

Pressing the ENTER button brings up the OSD main menu.

Item	Content
Auto Adjust	
Brightness/ Contrast	
Brightness	Adjust the backlight brightness
Contrast	Adjust the contrast ratio
Image adjust	
H. Position	adjust the horizontal position of display on screen
V. Position	adjust the vertical position of display on screen
Clock	adjust the pixel clock
Phase	Adjust the phase

Colour	
9300K	Set color temperature to 9300 Kelvin
7500K	Set color temperature to 7500 Kelvin
6500K	Set color temperature to 6500 Kelvin
Custom colour	Adjust color temperature to user defined value
OSD Setup	
H. Position	Adjust OSD horizontal position
V. Position	Adjust OSD vertical position
OSD timeout	Adjust OSD timeout
H. Position	Adjust OSD horizontal position
V. Position	Adjust OSD vertical position
Language	
Language	English, Français, Deutsch, Italiano, Polski, Español, Nederlands, , 日本語, 简体中文, Svenska, Português, Norsk, Suomi, Dansk, Русский, Türkçe, Český, עברית, عربي
Recall	
Miscellaneous	
Sharpness	Selection 1 - 5
DDC/CI	DDC/CI on/off
Information	Information about input signal
Adv. Contrast	Advanced contrast
Display Mode	Full screen/Keep aspect
Input Select	
AUTO	Select automatic input detection
Manual	Select manual D-sub / DVI / HDMI
Audio	
Volume	Adjust speaker volume
Mute	Select mute on/off
HDI Audio	HDMI / Line in